

词汇辅导:不良现象中英文对照表 PDF转换可能丢失图片或格式, 建议阅读原文

https://www.100test.com/kao_ti2020/261/2021_2022__E8_AF_8D_E6_B1_87_E8_BE_85_E5_c67_261123.htm 1.缺件(MISSING PARTS) 2.错件(WRONG PARTS) 3.多件(EXCESSIVE PARTS) 4.短路(SHORT) 5.断路(OPEN) 6.线短(WIRE SHORT) 7.线长(WIRE LONG) 8.拐线(WIRE POOR DDRESS) 9.冷焊(COLD SOLDER) 10.包焊(EXCESS SOLDER) 11.空焊(MISSING SOLDER) 12.锡尖(SOLDER ICICLE) 13.锡渣(SOLDER SPLASH) 14.锡裂(SODER CRACK) 15.锡洞(PIN HOLE) 16.锡球(SOLDER BALL) 17.锡桥(SOLDER BRIDGE) 18.滑牙(SCREW LOOSE) 19.氧化(RUST) 20.异物(FOREIGNER MATERIAL) 21.溢胶(EXCESSIVE GLUE) 22.锡短路(SOLDER BRIDGE) 23.锡不足(SOLDER INSUFFICIENT) 24.极性反(WRONG POLARITY) 25.脚未入(PIN UNSEATED) 26.脚未出(PIN UNVISIBLE) 27.脚未剪(PIN NO CUT) 28.脚未弯(PIN NOT BENT) 29.缺盖章(MISSING STAMP) 30.缺标签(MISSING LABEL) 31.缺序号(MISSING S/N) 32.序号错(WRONG S/N) 33.标签错(WRONG LABEL) 34.标示错(WRONG MARK) 35.脚太短(PIN SHORT) 36.J1不洁(J1 DIRTY) 37.锡凹陷(SOLDER SCOOPED) 38.线序错(W/L OF WIRE) 39.未测试(NO TEST) 40.VR变形(VR DEFORMED) 43.零件沾胶(GLUE ON PARTS) 41.PCB翘皮(PCB PEELING) 42.PCB弯曲(PCB TWIST) 44.零件脚长(PARTS PIN LONG) 100Test 下载频道开通, 各类考试题目直接下载。详细请访问 www.100test.com